

Images of the Interior of Gadsby's Tavern Museum's Historic Ice Well



Interior access to the ice well.



A view looking inside the ice well.



Plant growth on the interior brick.



View looking up at the original street level "hatch."



View looking up at the "cut away" viewing glass.



Crack monitoring of a collapsing portion of the ice well wall.



Views of the interior walls of the ice well.